



METER BASE JUMPER SETS

JF110-MELT-F -5

5 Meter Head Assembly Load & Source kit

Quantity	UM	Part No.	Description
1	EA	JSP4818-110	Meter base head (source) fused
1	EA	JSP4819	Meter base head (load)
4	EA	B94-1025	Strain relief grip
2	EA	RE64K	Reducer bushing
1	EA	J33-68036-K07	Male meltric plug
1	EA	J33-64036C-K07-843	Female meltric receptacle
2	EA	J6PH114	Handle assembly
10	M	4A WO-0203	# 2/3 Conductor cabtire cable (2x5) type SOW
1	M	5J-0201	# 6 Welding cable (neutral)
2	EA	FD96	Finger draw plate
2	EA	J-ORFT	Orange reflective tape
2	EA	J-YELL-6	Yellow heat shrink

JF110-MELT-F -1

1 Meter Head Assembly Load & Source kit

Quantity	UM	Part No.	Description
1	EA	JSP4818-110	Meter base head (source) fused
1	EA	JSP4819	Meter base head (load)
4	EA	B94-1.25	Strain relief grip
2	EA	RE64K	Reducer bushing
1	EA	J33-68036-K07	Male meltric plug
1	EA	J33-64036C-K07-843	Female meltric receptacle
2	EA	J6PH114	Handle assembly
2	M	4A WO-0203	# 2/3 Conductor cabtire cable (2x5) type SOW
1	M	5J-0201	# 6 Welding cable (neutral)
2	EA	FD96	Finger draw plate
2	EA	J-ORFT	Orange reflective tape
2	EA	J-YELL-6	Yellow heat shrink

JE-10-MELT**Extension 10 Meter**

Quantity	UM	Part No.	Description
1	EA	J33-68036-K07	Male plug
1	EA	J33-64036C-K07-843	Female receptacle
2	EA	J6-PH-114	Handle assemblies
10	M	4A WO-0203	# 2/3 Conductor cabtire cable (type SOW)
2	EA	FD 96	Finger draw plate
2	EA	B94-1.25	Strain relief grip
2	EA	RE64K	Reducer bushing
4	EA	J-YELL-6	Yellow heat shrink

JE-15-MELT**Extension 15 Meter**

Quantity	UM	Part No.	Description
1	EA	J33-68036-K07	Male plug
1	EA	J33-64036C-K07-843	Female receptacle
2	EA	J6-PH-114	Handle assemblies
15	M	4A WO-0203	# 2/3 Conductor cabtire cable
2	EA	FD 96	Finger draw plate
2	EA	B94-1.25	Strain relief grip
2	EA	RE64K	Reducer bushing
4	EA	J-YELL-6	Yellow heat shrink

JE-OH-15-ARL**Extension 15 meter**

Quantity	UM	Part No.	Description
1	EA	J33-60436C-K07-843	Female receptacle
1	EA	J6-PH611	Handle assembly
15	M	4A WO-0203	# 2/3 Conductor cabtire cable
1	EA	FD96	Finger draw plate
1	EA	B94-1.25	Strain relief grip
1	EA	RE64K	Reducer bushing

JF110-SCR-15**Head assembly (source) no connector**
(for connecting temporary construction sevice)
Description

Quantity	UM	Part No.	Description
1	EA	JSPH818-110	Meter base head (source) fused
1	EA	B94-1.25	Strain relief grip
1	EA	RE64K	Reducer bushing
15	M	4A WO-0203	# 2/3 Conductor cabtire cable (type SOW)
1	EA	5J-0201	# 6 Welding cable /meter
1	EA	WOO 36515	Strain relief bail grip.
2	EA	J-ORFT	Orange reflective tape

JF-LO-F-15**Head assembly (load) no connector**
(for connecting to overhead or padmount transformer)
Description

Quantity	UM	Part No.	Description
1	EA	JSPH4819	Meter base head (load)
1	EA	B94-1.25	Strain relief grip
1	EA	RE64K	Reducer bushing
15	M	4A WO-0203	# 2/3 Conductor cabtire cable (type SOW)
1	EA	5J-0201	# 6 Welding cable /meter
1	EA	WOO 36515	Strain relief bail grip
2	EA	JJN110	110 amp fuse